Monday, 5/15/2006 11:14:23 AM Date: Linda Lacelle User: : CC-DAR01 Dart Aerospace Ltd. Customer Job Number : 27129 : 10804 **Estimate Number** :NIA P.O. Number : 5/15/2006 S.O. No. : NIA This Issue Prsht Rev. : NC : N/A First Issue : 27040 **Previous Run** SER COMMENT BELOW Written By **Checked & Approved By** Comment **Additional Product** Job Number: Seq. #: WATER JET 1.0

Process Sheet

Drawing Name

: D2877

Part Number Drawing Number : D2877 : Z_CUSTOM

Project Number

: NIA

Drawing Revision

AIN:

Material **Due Date** :NIA

: 5/22/2006

Qty:

24 Um:

Each



: NIA

Machine Or Operation:

Description:

FLOW WATER JET



Comment: FLOW WATER JET

MAKE PER DRWG D2877 REV.B

2.0

M5052H32S125

5052-H32 .125 Sheet



Comment: Qty.:

0.0500 sf(s)/Unit Total:

1.2000 sf(s)

5052-H32 .125 Sheet

ol 05 15

3.0

WATER JET

FLOW WATER JET



Comment: FLOW WATER JET

DEBURR

SAD



4.0

QC5

INSPECT WORK TO CURRENT STEP



26

Comment: INSPECT WORK TO CURRENT STEP

HAND FINISHING 5.0

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

ACID ETCH & ALODINE

SAN

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1 **IDENTIFY & STOCK**

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector			
										

NCR:		\	WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B	· · · · · · · · · · · · · · · · · · ·	Verification		Approval					
DATE	STEP	Section A	Initial Design Mgr	Initial Action Description Sign &		Section C	Approval Design Mgr	Approval QC Inspector					
	•												

Part No:	PAR #:	Fault Category: NCF	₹:	Yes No DQA:	Date: <u>06/05/15</u>
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: User:

Monday, 5/15/2006 11:14:23 AM

Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D2877

Job Number: 27129

Part Number: D2877

Job Number:

Seq. #:

Machine Or Operation:

Description:

7.0

DOCUMENT CONTROL

Comment: DOCUMENT CONTROL

INSPECT LEVEL 21

Job Completion



D 06/05/15

Dart Aerospace Ltd


W/O:			WOR	K ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE		E	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
						,			
NCR:			WORK ORDER	NON-CONFORMANC	E (NCR)			
	STEP	Description of NC	Description of NC Corrective Action Section B			Verific	ation	Approval	Approval
DATE		Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Secti		Design Mgr	QC Inspecto
			,						
Part No	*	PAR #:	Fault Category:	NCR: Y	es No	DQA:		Date:	
NOTE: D	ate & initia	al all entries		C	A: N/C CI	osed:		Date:	





DESIG	4	DRAWN	BY P	l.	AEROSPACE LTD KESBURY, ONTARIO, CANADA	
CHEC	AA .	APPRO	ED /	DRAWING NO. D2877	SHEE	REV. A
DATE		7		TITLE	*** <u></u>	SCALE
99.0	2.23			SADDLE SPACE	ER	1:1
Δ		99 7	12 23	NEW ISSUE		

RELEASED 99.04.27 B



MATERIAL: 5052-H32/H34 (QQ-A-250/8) 0.100 THICK FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4.1 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED BREAK ALL SHARP EDGES 0.010 TO 0.020

Dart Aerospace Ltd

W/O:			WOR	K ORDER CHANGES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date Qty	Approval Mfg / Design Mgr	Approval QC Inspector
			WORK ORDER	NON-CONFORMANC	F (NCR			
NCR:			WORK ORDER NON-CONFORMANCE (NCI Corrective Action Section B			·)		<u> </u>
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector
	,							
į								
Part No):	PAR #:	Fault Category:	NCR: Y	es No	DQA:	Date:	
	ate & initial a				A: N/C CI		— — — Date:	

Linda Lacelle

From:

Bill Beckett [bbeckett@dartaero.com]

Sent:

Monday, May 15, 2006 10:38 AM

To:

pmcdonald@dartaero.com

Cc:

heatherm@dartaero.com; Dale Trepanier (E-mail); Linda Lacelle (E-mail); Brigitte Golden (E-

mail); Sue Bedford (E-mail)

Subject:

RE: Apical float skid gear

Peggy,

Grrrrr!!!...but what can we do!?

We hope to be able to send another set today. We don't have any extras, but

we will load up on the Waterjet ASAP.

I assume you will send us a "no-charge" order for these.

Bill

PS: Dale - there should be a CSR reference given to Peggy for this.

----Original Message----

From: Peggy Mcdonald [mailto:pmcdonald@dartaero.com]

Sent: "-" 15, 2006 10:25 AM

To: '!
Cc: h
Subje

Bill PLea Tha Peg ---Fr Se TC CS I MACH

247

27040

Hello Peggy,

Would you please send another set or surreach the right department and we can't find them.

.t us never

ip.

Please send them to my attention and provide w/b.

Thanks. Eric

----Original Message----

From: Auger, Ghislain

Sent: Monday, May 15, 2006 9:00 AM

To: Couture, Michel; Corbeil, Luc; Laty, Eric

Cc: Bastien, Jean-Francois; Lavoie, Julie

Subject: RE: Apical float skid gear

Importance: High

Eric can you go back to Dart to order other shims we can't find the package and the job need to be complete.

Thanks!

----Original Message----

From: Couture, Michel

Sent: Friday, May 12, 2006 1:13 PM To: Auger, Ghislain; Corbeil, Luc

Cc: Bastien, Jean-Francois; Lavoie, Julie

Subject: RE: Apical float skid gear

Pour votre info. en ce merveilleux vendredi 13:15 hre ce colis n'est toujours pas en ma possession . m.c.

----Original Message----

From: Auger, Ghislain

Sent: Thursday, May 11, 2006 7:15 AM

To: Couture, Michel

Subject: FW: Apical float skid gear

Peut-tu verifier et donner les pieces a Luc Corbeil. Merci!

----Original Message----

From: Bill Beckett [mailto:bbeckett@dartaero.com]

Sent: Wednesday, May 10, 2006 4:13 PM

To: Auger, Ghislain

Cc: pmcdonald@dartaero.com; Laty, Eric; 'David Shepherd'

Subject: RE: Apical float skid gear

Ghislain, This was shipped May 8.

FedEx Priority overnight Tracking no: 792091801091

Attention: Eric Laty

It was received at Mirabel 10:00 am on May 9 and signed for by a Mr. Gagnon.

Let me know ASAP if you need any further information or help.

Best Regards, Bill Beckett General Manager Dart Aerospace 1270 Aberdeen Street Hawkesbury, Ontario K6A 1K7 Canada Ph (613) 632-3336 Fax (613) 632-5246 Cell (514) 862-7585 bbeckett@dartaero.com www.dartaero.com

----Original Message----From: Auger, Ghislain [mailto:GAuger@bellhelicopter.textron.com]

Sent: May 10, 2006 9:37 AM

To: Laty, Eric; 'David Shepherd'

Cc: 'pmcdonald@dartaero.com'; 'Bill Beckett'

Subject: RE: Apical float skid gear

No new about that ??

Eric can you take care of that?

----Original Message----

From: Laty, Eric

Sent: Friday, May 05, 2006 11:00 AM To: Auger, Ghislain; 'David Shepherd'

Cc: 'pmcdonald@dartaero.com'; 'Bill Beckett'

Subject: RE: Apical float skid gear

Please send them to my attention and provide Fedex P1 W/B.

Thanks.

Eric Laty Acheteur Bell Helicopter TEXTRON elaty@bellhelicopter.textron.com 12800, rue de l'Avenir Mirabel (Québec) J7J 1R4 Canada

Tel: (450) 971-6500 ext 2441

Fax: (450) 437-2848

----Original Message----

From: Auger, Ghislain

Sent: Friday, May 05, 2006 7:19 AM

To: 'David Shepherd'

Cc: pmcdonald@dartaero.com; Bill Beckett; Laty, Eric

Subject: RE: Apical float skid gear

Importance: High

We need these shims for lh and rh for six aircrafts ,if possible as soon as you can because we wait about that to complete this installation for flight check.
Thanks!

Eric , can you take care of that?

----Original Message----

From: David Shepherd [mailto:davids@dartaero.com]

Sent: Thursday, May 04, 2006 4:31 PM

To: Auger, Ghislain

Cc: pmcdonald@dartaero.com; Bill Beckett; Laty, Eric

Subject: Re: Apical float skid gear

Ghislain,

I have discussed with Bill Beckett, and Dart will provide thicker shims for you to try out early next week. Do you need them for both saddles (LH and RH) or just one side. And how many aircraft? Just one?

Thanks, David

---- Original Message -----

From: "Auger, Ghislain" <GAuger@bellhelicopter.textron.com>

To: "'David Shepherd'" <davids@dartaero.com>

Cc: <pmcdonald@dartaero.com>; "Bill Beckett" <bbeckett@dartaero.com>; "Laty,

Eric" <ELaty@bellhelicopter.textron.com> Sent: Thursday, May 04, 2006 12:57 PM Subject: RE: Apical float skid gear

```
> We already followed that procedure ,as per the installer he torqued to the
> upper range and followed the pattern mentioned
> in the IIN .Finally rechecked all torques. We still with this situation.
> Best Regards.
> ----Original Message----
> From: David Shepherd [mailto:davids@dartaero.com]
> Sent: Thursday, May 04, 2006 2:21 PM
> To: Auger, Ghislain
> Cc: pmcdonald@dartaero.com; Bill Beckett; Laty, Eric
> Subject: Re: Apical float skid gear
> Ghislain,
> Before we do anything too drastic here, just wanted to check a couple of
> things:
> 1) The IIN gives a torque range on all saddle bolts. If you are not
working
> to the upper range, I would suggest that in this case, you work to the
upper
> range on all bolts.
> 2) After you have torqued everything up, have you gone through the torque
> pattern a second time to ensure that you are holding the upper torque
> values.
> Thanks for your patience.
> David
> ---- Original Message -----
> From: "Auger, Ghislain" <GAuger@bellhelicopter.textron.com>
> To: "'David Shepherd'" <davids@dartaero.com>
> Cc: <pmcdonald@dartaero.com>; "Bill Beckett" <bbeckett@dartaero.com>;
"Laty,
> Eric" <ELaty@bellhelicopter.textron.com>
> Sent: Wednesday, May 03, 2006 11:56 AM
> Subject: RE: Apical float skid gear
> > David ,
> > Here is the information you ask me ,the diameter of the tube in the
saddle
> > is 3.00 inches.
> > Sorry you're right the gap was 0.090.
> > I've attached some picture of the installation.
> > Thanks!
> >
> >
> >
>> ----Original Message----
> > From: David Shepherd [mailto:davids@dartaero.com]
> > Sent: Wednesday, May 03, 2006 11:24 AM
> > To: Auger, Ghislain
> > Cc: pmcdonald@dartaero.com; Bill Beckett; Laty, Eric
> > Subject: Re: Apical float skid gear
> >
> > You must mean 0.090 gap. Can you take a picture to show me exactly
where
                       There should be no gap at the top and a small gap at
> > this 0.090 gap is.
> > bottom. Also, what is the OD of the crosstube cuff going into saddle.
```

```
> >
> > Thanks,
> > David
> >
> >
>> ---- Original Message -----
>> From: "Auger, Ghislain" <GAuger@bellhelicopter.textron.com>
> > To: "'David Shepherd'" <davids@dartaero.com>
> > Cc: <pmcdonald@dartaero.com>; "Bill Beckett" <bbeckett@dartaero.com>;
> "Laty,
> > Eric" <ELaty@bellhelicopter.textron.com>
> > Sent: Wednesday, May 03, 2006 6:35 AM
> > Subject: RE: Apical float skid gear
> >
> >
> > > We know as per your previous email that the gap is acceptable to you
but
> > presently we have an other skid gear with about .90 gap at the aft
> > crosstube saddle even with the d2876 saddle spacer installed.My
question
> > is
> > :is it acceptable to modified the spacer to close the gap and if it's
> > > the case can you provided us a thicker shim.
> > > Best Regard!
> > >
> > > Ghislain Auger
> > BELL HELICOPTER (CANADA)
> > > Technologue IV
>>> (450)971-6500 ext:3394
> > > Beeper: *73-261
> > Email:gauger@bellhelicopter.textron.com
> > >
> > >
> > >
>>> ----Original Message----
> > From: David Shepherd [mailto:davids@dartaero.com]
> > Sent: Monday, April 10, 2006 4:31 PM
> > > To: Auger, Ghislain
> > > Cc: pmcdonald@dartaero.com; Bill Beckett
> > > Subject: Re: Apical float skid gear
> >
> > >
> > The gap shown in the pictures is acceptable (and typical) as long as
you
> > respect the torques in the Dart Installation Instructions. You should
> > find
> > > that the gap is closed at the top, but the important thing is that you
> > > don't overtorque.
> > >
> > > David
> >
> > >
>>> ---- Original Message ----
> > From: "Auger, Ghislain" <GAuger@bellhelicopter.textron.com>
> > To: <davids@dartaero.com>
> > Sent: Monday, April 10, 2006 1:43 PM
> > Subject: FW: Apical float skid gear
> > >
> > >
> > > As per Discuss with Peggy on that issue,
> > > Do you have any developments?
> > > >
> > > >
>>>> > ----Original Message----
>>>> From: Auger, Ghislain
>>>> Sent: Friday, April 07, 2006 1:27 PM
>>>> To: 'peggy@dartaero.com'
```

```
>>>> Cc: Corbeil, Luc; Lavoie, Julie
>>>> Subject: Apical float skid gear
> > > > >
> > > >  Peggy,
> > > >
> > > > I have a question regarding the installation of the apical float
> skid
> > > gear
>>>> D412-664-203 for the saddle installation on the aft crosstube.
>>>> Is it acceptable to have a gap in beetween the saddle even if we
> > > followed
> > > > the torque sequence of the IIND412-742 P.6 figure 1?
> > > > Thanks!
> > > >
>>>> I've attach a document to show you the situation.
> > > >
> > > > > <<APICAL SKID BOOTS PICTURES.xls>>
> > > >
>>>> Shislain Auger
> > > > BELL HELICOPTER (CANADA)
>>>> Technologue IV
>>>>> (450)971-6500 ext:3394
> > > > Beeper:*73-261
>>>> Email:gauger@bellhelicopter.textron.com
> > > >
> > > >
> > >
> > >
> >
> >
> >
```

>

DART AEROSPACE LTD	Work Order: 27129
Description:	Part Number: D2877
Inspection Dwg: Rev:	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.35	+/- 0.030	3,35	J		vern	
2,35	1/-0.030	2.32	√ _		ylfn	
0.250	+0.030-0000	0.250	$\sqrt{}$		1860	
Ø 0.257	+/-0.010	0.254	<u> </u>		vern	
		:				
				1		
						100
						- Jp

Measured by: M. M	Audited by:	Prototype Approval:	
Date: 05 05 15	Date: 06-05-15	Date:	

Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/JLM	